SAFETY CERTIFICATE OF TEMPORARY BUILDINGS (KENDRIYA VIDYALAYA SAMBA)

Sr.	Name of KV	KV Samba(J&K)
No.		
L	Name/ No of Temp Buildings (Adm & Secondary Block)	T-17, T-19, T-61, T-62, T-109, T-13, T-114, T-120, T-127, T-134, T-136, T-142, T-143, T-144, T-156, T-157, T-162 & T-49
2	Primary Block	Bldg 1 T-28 Bldg 2 T-29
3	Whether Buildings are safe	Yes, except the following buildings:- (a) Bldg No T-61 and T-18 (secondary wing) due to deteriorate Roof of AC sheets, wooden rafter/ Purlims and false ceiling (to be carried out in spl repairs)
4	Major/Minior structural repair projected by Vidyalaya	Bldg T-61 and T-18 projected for spl repairs for 2021-22.
5	Major/Minior structural repair done by sponsoring agency during current year	T-19 and T-127 structural repair done under special repair during session 2020-21
6	Additional requirements of classrooms/Accommodations are provided by the sponsoring agency	NO
7	Space of the school is adequate	YES
8	Whether water/electric supply and sanitary facilities are provided by the sponsoring by the sponsoring agency	YES

Dated: 19/03/2021

AGE(MAINT)

AE (civil)

AGE B/R Samba

Garrison Engineer Samba

Garrison Engineer

COUNTERSIGNATURE

अध्यक्ष / CHAIRMAN विद्यालय प्रबन्धक समिति Vidyalaya Management Committee केन्द्रीय विद्यालय साम्बा Kendriya Vidyalaya Samba