## Office of the Joint Director Fire & Emergency Services Jammu Range, Jammu

The Principal Kendriya Vidyalaya Samba.

No: JDJF&ES/FP/ //66

Dated: 6 .03.2021

Sub: Fire Safety Certificate.

Ref: Your Letter No.240371/KV/SMB/2019-20 dated: 11.01.2021.

Sir,

The inspection of above said school was got carried out by the inspecting officer of this department. During inspection it was found that the management has installed First Aid Fire Extinguishers in their school premises. Besides this one underground water storage tank of 20 KL Capacity is also available there. The school is about 06 Km away from Fire & Emergency Station Samba and is approachable for fire appliances in case of any emergency. Since the school is already functioning as such, the management can proceed ahead for operation subject to adopt the following fire safety precautionary measures in letter and spirit for betterment of the school:-

All exits/entrances should be kept open and free from any obstruction for easy and 1.

safe evacuation of inmates during any emergency.

First Aid firefighting system installed in the school building should be checked 2. periodically. Staff and students should be fully trained in handling/operating of firefighting system installed in the School building. The management shall intimate the office of Assistant Director, Fire & Emergency Services Command Samba-Kathua after each quarter that the firefighting equipment installed in the school are functioning.

All class rooms and examination halls having seating capacity for more than 45 3.

students need to be provided with two exits.

The corridor of the building shall not be used for any kind of storage. 4.

No Hazardous material should be kept inside of the school premises (especially LPG 5. cylinder, Petrol and Diesel etc.). Any deviation found in this regard, this clearance will be treated withdrawn/cancelled.

One window of each class room should be without iron grill so that it can be used for 6.

safe evacuation of inmates during any mishap.

There is only one staircase existing in the building, so it is the whole responsibility of 7. the management to keep the fire fighting system functional and evacuation of inmates in case of any fire incident.

The management of the school shall be wholly and solely responsible for keeping the 8. firefighting system in working condition 24x7 and safe evacuation of its students

during any mishap.

At present school is having two single storied cemented sheet roofed blocks. As such 9. no addition/alteration should be made by the school management in the existing structure without prior permission from this department. Any deviation found in this regard, this clearance will be treated withdrawn/cancelled.

Telephone numbers of nearest Fire & Emergency Stations should be displayed. The validity of this clearance shall remain in force for one year and same needs to be renewed after checking of firefighting system installed in the school.

🎉 Jammu Range, Jammu